

KLIK STAIRWELL INSTRUCTIONS

ENSURE ALL PARTS ARE PRESENT BEFORE ERECTION

- 8) Dismantling is the reverse of erection.
- 7) Stand on the platform and fit toe boards
- 6) Still sitting through the trap fit 4 horizontal frames
- 5) Sit through the trap and fit the tall and short guardrail as shown
- 4) Position the platform with the trapdoor to the front.
- 3) Add frame and engage interlock clips.
Fit the upper diagonal brace.
- 2) Fit the horizontal brace above the designated location collar.
Level the tower by using the adjustable legs.
Fit the lower diagonal braces as shown.
- 1) Insert legs into the frame.



ALWAYS CLIMB ON THE INSIDE OF THE TOWER.

MAXIMUM SAFE WORKING LOAD FOR THE PLATFORM/STRUCTURE 150KGS